

Date of Incident	07-31-2023
Prepared By	Joseph Cooper
Reviewed By	Incident Report was reviewed by Alison Snyder on 08-01-2023 at 07:54 PM.
Property	Gardens of Mt. Airy
Time of Incident	03:00:00
Location of Incident	Elevator room

1	-:-		Type	_
ın	cia	ent	IVD	-

**Mechanical Disruptions** 

## **Incident Type Category**

Plumbing or Sprinkler leak

# **Description of Incident**

The elevator began acting erratically. Upon entering the elevator room, we found that the mini split (elevator ac unit) condensation leaked into the elevator room causing water to get on the control panel.

#### Corrective action taken at the time of the incident

Elevator shut down and signs posted on each floor. Joe cleaned up the water, and placed a dehumidifier and fan in the room to dry it out. Tom from Pincus visited on Tues 8/1 to view the control panel and make a recommendation on next steps. He stated the equipment needs to dry out for several days until it can be worked on. More information to follow.

# What we have done related to Customer Service and helping the resident, if anything?

Communication sent to residents regarding outage. Will continue communication to alert residents of outage and timeline expected.

# Witnesses names and phone number

Joe Cooper 267-637-4017

# Was there security camera footage of this incident?

No

# Link to security footage video in Box

http://

### Did this incident involve a resident?

No

## Did this incident involve a Lindy team member?

No

### Did this incident involve a vendor?

No



