

## Maintenance Request Added On : 04-28-2025

See Attached Photo for More Detail

Category	Preventative Maint
SubCategory	Other
Property	Joshua House
Reported by	Thomas Hines
Issue Note	( Building I-South / Rear ) Three areas of missing downspouts in rear of building. Along with missing Electrical Box Cover.

