

## Maintenance Request Added On : 05-08-2025

See Attached Photo for More Detail

<b>Category</b>	<b>Roof</b>
<b>SubCategory</b>	<b>Other</b>
<b>Other Description</b>	<b>Missing/Damaged Shingles</b>
<b>Property</b>	<b>Meadowbrook</b>
<b>Reported by</b>	<b>Thomas Hines</b>
<b>Issue Note</b>	<b>Damaged and missing shingles around down spout.</b>

