

## $Maintenance\ Request\ Added\ On: 06\text{-}04\text{-}2025$

## See Attached Photo for More Detail

Category	Other
SubCategory	Other
Other Description	Down Spout Pipe
Property	Warrington Crossings
Reported by	Thomas Hines
Issue Note	Section of down spout pipe is missing and needs replacing.

