



Date of Incident	03-14-2024
Prepared By	Joseph Cooper
Reviewed By	Incident Report was reviewed by Joseph Cooper on 03-14-2024 at 01:42 PM.
Property	Willow Bend
Time of Incident	01:33:00
Location of Incident	Fence behind C building

Report Last Updated By	Update Date
Joseph Cooper	03-14-2024

# **Incident Type**

**Property Damage** 

## **Description of Incident**

A number of unknown vehicles have been pulling in and stationing behind sea building throughout the night on multiple nights. These vehicles are not registered to the property. The vehicles have backed into the fence on several occasions, thus damaging and bending the fence. The vehicle in the picture is currently parked in the spot pressed up against the fence. Tan Buick Vehicle license plate is Pa temp plate 3107003 DIN 947297

#### Corrective action taken at the time of the incident

Took photos filed report

## What we have done related to Customer Service and helping the resident, if anything?

N/a

# Witnesses names and phone number

N/a

# Was there security camera footage of this incident?

No

## Link to security footage video in Box

http://

### Did this incident involve a resident?

No

### Did this incident involve a Lindy team member?

No

### Did this incident involve a vendor?

No





