

<b>Date of Incident</b>	08-20-2025
<b>Prepared By</b>	Stephen Cicala
<b>Reviewed By</b>	Incident Report was reviewed by Stephen Cicala on 12-19-2025 at 05:25 AM.
<b>Property</b>	251 Dekalb
<b>Time of Incident</b>	11:15:00
<b>Location of Incident</b>	West tower 1- rear tower.

<b>Report Last Updated By</b>	<b>Update Date</b>
Stephen Cicala	08-21-2025

Incident Type
Misc.
Description of Incident
Fire alarm went off. When the fire department arrived, it was found the smoke detector on the 7th floor, of West tower 1- rear tower, was at fault. The smoke detector is located in the common hallway, outside apartment W725. No fire or smoke in the apartments or in the common hallway. Possibly a faulty smoke detector.
Corrective action taken at the time of the incident
The fire department gave the ok, reset the fire panel, and residents were allowed back into the tower.
What we have done related to Customer Service and helping the resident, if anything?
The management office and maintenance team contacted Kartman/Thompson Safety to schedule inspection of the smoke detector in the common hallway.
Witnesses names and phone number
n/a
Was there security camera footage of this incident?
No
Link to security footage video in Box
http://
Did this incident involve a resident?
No
Did this incident involve a Lindy team member?
No
Did this incident involve a vendor?
No
Should this incident be reported to the residents renters insurance policy?
No