

Date of Incident	12-26-2022
Prepared By	Jeff Wilson
Reviewed By	Incident Report was reviewed by Jeff Wilson on 12-28-2022 at 02:40 PM.
Property	450 Green Apartments
Time of Incident	11:00:00
Location of Incident	N Building unit N102

Incident Type	
echanical Disruptions	
Incident Type Category	
umbing or Sprinkler leak	
Description of Incident	
ater supply line in the ceiling of unit N102 froze and burst, flooding out unit. L&L heating came out to make repairs and restore heat to buildings.	
Corrective action taken at the time of the incident	
ontacted L&L to make repairs and restore heat to buildings. Also contacted Cleantech for emergency water evacuation for unit and hallway.	
What we have done related to Customer Service and helping the resident, if anything?	
ontacted resident and reserved room at Hampton Inn.	
Witnesses names and phone number	
/A	
Was there security camera footage of this incident?	
0	
Link to security footage video in Box	
ttp://	
Did this incident involve a resident?	
es	
Resident Name	
yler Arsenault	
Did this incident involve a Lindy team member?	
0	
Did this incident involve a vendor?	



No



