

Maintenance Request Added On : 04-01-2025

See Attached Photo for More Detail

Category	Painting
SubCategory	Other
Other Description	possible downspout repair
Property	Gardens of Mt. Airy
Reported by	Thomas Hines
Issue Note	Top floor peeling ceiling under downspout area in rear of building. Thank you .

