



Manager: Billie Schott

Business Purpose: apt 521 stove parts

Is this a Credit/Return: No

Vendor Code: fb4732

Card Name: Firsttrust Bank

Card Unit:

Card Receipt Total: \$126.27

Card Purchase Date: Jan-15-2021

Same Expense Code Per Property?: No

Same Description Per Property?: No

Card Purchase for Only One Property: Yes

Card Allocation Method: Split Evenly

Building	Code Allocation Method	Property Cost	Property Unit#	Expense Code	Code Name	Code Desc	Expense Code Cost
Crossings at Stanbridge	Split Evenly	\$126.27		56110	Appliance Repair Supplies	Apt 521 stove parts	\$126.27

1/15/2021 Invoice - AppliancesPros.com

AppliancePartsPros.com, Inc.™
1-877-477-5278

INVOICE

SOLD TO:
Billie Schott
Lindy Apartments Management
300 E. 1st St.
Suite 211
Lindby, MO 64646
(314) 888-8888

SHIP TO:
Billie Schott
Crossings At Stanbridge
44 Stanbridge Avenue
Lindby, MO 64646
(314) 888-8888

Order Number: 12452126
Ship Method: Standard

Payment Method: Credit Card
Reference Number:

C Code:

Order	Ship	R/O	Part Number	Description	Unit Price	Total
1	0	0	APR080101 (2500000001)	Control	\$96.45	\$96.45
1	0	0	APR048311 (334320728)	OVERLAY	\$29.72	\$29.72

Page 1 of 1

Please refer to our website for more information: <http://www.appliancespros.com>

Thank you for ordering from AppliancePartsPros.com!

Sub Total: \$126.17
Tax: \$0.10
Shipping & Handling: \$0.00
Total: \$126.27