



Date of Incident	07-22-2025
Prepared By	Jason Aleman
Reviewed By	The Incident Report was Not reviewed.
Property	251 Dekalb
Time of Incident	10:20:00
Location of Incident	Kitchen stove gas line of S502

Report Last Updated By	Update Date
Brian Kroker	07-24-2025

Incident Type Misc. **Description of Incident** Resident smelled gas and started feeling a little off. She called 911 and the fire department was dispatched. Resident then went to office to report to maintenance. Jason and Dominic accompanied Fire Dept two unit. Found fire vert solenoid valve leaking gas. Corrective action taken at the time of the incident Fire revert solenoid valve replaced. Line test tested with gas leak detector. Fire Avert express mailed to the company for testing. What we have done related to Customer Service and helping the resident, if anything? Resident was present through incident Witnesses names and phone number Erica S502 610-636-0270 Jason 2678956576 Dominic 2675061149 Was there security camera footage of this incident? No Link to security footage video in Box http:// Did this incident involve a resident? Yes Unit S0502 **Resident Name** Frica Haldeman Did this incident involve a Lindy team member? No Did this incident involve a vendor? No

Should this incident be reported to the residents renters insurance policy?



No