

## Maintenance Request Added On : 03-31-2025

See Attached Photo for More Detail

Category	Common Area
SubCategory	Hallway
Property	Mt. Airy Place
Reported by	Thomas Hines
Issue Note	The entrance floor( next to door) is slippery, due to humidity? Either way, a small rug needs to be at spot or large rug re-positioned. Thank you.

