

Maintenance Request Added On : 04-15-2025

See Attached Photo for More Detail

Category	Electrical
SubCategory	Outlets
Property	Towers at Wyncote
Reported by	Thomas Hines
Issue Note	Tower#1- Exterior outlets need covering replacements along both sides of patio front wall .

