

Maintenance Request Added On : 05-14-2025

See Attached Photo for More Detail

Category	Common Area
SubCategory	Stairwell
Property	Regency House
Reported by	Thomas Hines
Issue Note	2nd Floor / East Stairway Balcony/ Railing is extremely loose; broken off from top right and other bolts need tightening.

