

LINDY PROPERTY MANAGEMENT CO SUITE 211 309 YORK RD JENKINTOWN PA 19046

File No. 8509

Location: WARRINGTON CROSSINGS - J BUILDIN

1700 STREET RD

WARRINGTON PA 18976

RE: NOTICE OF VIOLATION

On 1/17/2025, Inspector Austin Young conducted an inspection at the above-referenced location on equipment 245269B and found violations of the Boiler Law(35 P.S. §§ 1331.1-1331.19) and the Law's regulations (34 Pa. Code §§ 3a.1-3a.171). These violations are attached to this letter.

You have 30 days to correct these violations, complete the certification at the end of this notice, and submit it to my attention. A follow-up inspection may be conducted to confirm completion of the corrective action. All violations must be corrected prior to the issuance of a Certificate of Operation. If you already have a Certificate of Operation, failure to correct these violations may result in the equipment being placed out of service and/or administrative fines under 35 P.S. §§ 1331.17-1331.18.

INDUSTRIAL BOARD PROCEDURE

ANY INDIVIDUAL AGGRIEVED BY THIS NOTICE MAY APPEAL TO THE PENNSYLVANIA INDUSTRIAL BOARD. AN INDIVIDUAL MAY ALSO MAKE A REQUEST FOR AN EXTENSION TO COMPLY WITH THIS NOTICE AND/OR REQUEST A VARIANCE FROM THE APPLICABLE REGULATIONS AND TECHNICAL STANDARDS. INDUSTRIAL BOARD FORMS ARE FOUND ON THE DEPARTMENT'S WEBSITE AT www.dli.pa.gov (KEY WORD: INDUSTRIAL BOARD FORMS). WHEN FILING AN APPEAL OR REQUEST WITH THE INDUSTRIAL BOARD, REFER TO THE FILE NUMBER FOUND ABOVE AND FULLY SET FORTH THE REASON FOR YOUR APPEAL, REQUEST FOR AN EXTENSION OF TIME, OR VARIANCE REQUEST. YOUR COMPLETED FORM MUST BE SENT TO: INDUSTRIAL BOARD, 651 BOAS STREET, ROOM 1622, HARRISBURG PENNSYLVANIA 17121 ALONG WITH PAYMENT.

For quickest resolution or questions, please first contact the inspector Austin Young at atyoung@travelers.com or Ph# 267-453-0170 with questions prior to contacting the main office.

Respectfully,

William J. Ross

Director Boiler Division

All information provided on this certification is subject to the penalties of 18 Pa.C.S. § 4904 (relating unsworn falsification to authorities).			
Signature	Date		

Please sign and return this completed statement using one of the following methods:

8509 on equipment 245269B have been corrected.

- 1. **(preferred response method)**Send an email *with the signed letter attached* to the original inspector atyoung@travelers.com.
- 2. (alternate response method) Send an email with the signed letter attached to the boilers division Boilers@pa.gov.
- 3. (alternate response method) Send the signed letter using traditional mail postal service to:

FINDING NO.1: The low water cutoff device installed on the boiler requires repair or replacement to ensure that it will interrupt the flow of fuel before the water level falls below the lowest safe permissible water level established by the boiler manufacturer. Replacement LWCO's shall conform to CSD-1. Ref: Act 85, 104, PA 34 3a.4, 3a.51, 3a.61, NBIC (Edit 342)





LINDY PROPERTY MANAGEMENT CO SUITE 211 309 YORK RD JENKINTOWN PA 19046

File No. 8509

Location: WARRINGTON CROSSINGS - J BUILDIN

1700 STREET RD

WARRINGTON PA 18976

RE: NOTICE OF VIOLATION

On 1/17/2025, Inspector Austin Young conducted an inspection at the above-referenced location on equipment 307812B and found violations of the Boiler Law(35 P.S. §§ 1331.1-1331.19) and the Law's regulations (34 Pa. Code §§ 3a.1-3a.171). These violations are attached to this letter.

You have 30 days to correct these violations, complete the certification at the end of this notice, and submit it to my attention. A follow-up inspection may be conducted to confirm completion of the corrective action. All violations must be corrected prior to the issuance of a Certificate of Operation. If you already have a Certificate of Operation, failure to correct these violations may result in the equipment being placed out of service and/or administrative fines under 35 P.S. §§ 1331.17-1331.18.

INDUSTRIAL BOARD PROCEDURE

ANY INDIVIDUAL AGGRIEVED BY THIS NOTICE MAY APPEAL TO THE PENNSYLVANIA INDUSTRIAL BOARD. AN INDIVIDUAL MAY ALSO MAKE A REQUEST FOR AN EXTENSION TO COMPLY WITH THIS NOTICE AND/OR REQUEST A VARIANCE FROM THE APPLICABLE REGULATIONS AND TECHNICAL STANDARDS. INDUSTRIAL BOARD FORMS ARE FOUND ON THE DEPARTMENT'S WEBSITE AT www.dli.pa.gov (KEY WORD: INDUSTRIAL BOARD FORMS). WHEN FILING AN APPEAL OR REQUEST WITH THE INDUSTRIAL BOARD, REFER TO THE FILE NUMBER FOUND ABOVE AND FULLY SET FORTH THE REASON FOR YOUR APPEAL, REQUEST FOR AN EXTENSION OF TIME, OR VARIANCE REQUEST. YOUR COMPLETED FORM MUST BE SENT TO: INDUSTRIAL BOARD, 651 BOAS STREET, ROOM 1622, HARRISBURG PENNSYLVANIA 17121 ALONG WITH PAYMENT.

For quickest resolution or questions, please first contact the inspector Austin Young at atyoung@travelers.com or Ph# 267-453-0170 with questions prior to contacting the main office.

Respectfully,

William J. Ross

Director Boiler Division

8509 on equipment 307812B have been corrected	•
All information provided on this certification is su unsworn falsification to authorities).	ubject to the penalties of 18 Pa.C.S. § 4904 (relating to
Signature	Date

Please sign and return this completed statement using one of the following methods:

- 1. (preferred response method)Send an email with the signed letter attached to the original inspector atyoung@travelers.com.
- 2. (alternate response method) Send an email with the signed letter attached to the boilers division Boilers@pa.gov.
- 3. (alternate response method) Send the signed letter using traditional mail postal service to:

FINDING NO.1: The safety relief valve(s) leaks through at the seat and disk. Repair/replace the safety valve(s) with an ASME safety relief valve designed for service. A set pressure of not greater than psi and with a capacity of not less than lbs/hr. All safety valve repairs will be done by a company holding a National Board (VR) repair certificate. The valve(s) must be installed on the boiler proper with the spindle in the vertical position and without reducing the cross sectional areas of the inlet and outlet. Steam boilers exceeding 500 lbs/hr operating capacity shall discharge to the outside atmosphere. Piping shall be installed and supported so as not to induce a strain on the safety valve(s). Ref: Act 85, 104, PA 34 3a.4, 3a.26, 3a.29, 3a.51, 3a.61 (Edit 301).

FINDING NO.2: Leakage has developed at the . If a welded repair to an ASME vessel/boiler is required it shall be made in accordance with the requirements of the most current edition of the National Board Inspection Code, performed by a company holding a National Board "R" stamp and documented on a National Board "R-1" form. Repairs without welding and or not part of the vessel/boiler do not require National Board Inspection Code involvement. Ref: Act 85, 104, PA 34 3a.3, 3a.81, 3a.82, 3a.83, 3a.114, 3a.115, NBIC (Edit 327)



LINDY PROPERTY MANAGEMENT CO SUITE 211 309 YORK RD JENKINTOWN PA 19046

File No. 8509

Location: WARRINGTON CROSSINGS - J BUILDIN

1700 STREET RD

WARRINGTON PA 18976

RE: NOTICE OF VIOLATION

On 1/17/2025, Inspector Austin Young conducted an inspection at the above-referenced location on equipment 289285B and found violations of the Boiler Law(35 P.S. §§ 1331.1-1331.19) and the Law's regulations (34 Pa. Code §§ 3a.1-3a.171). These violations are attached to this letter.

You have 30 days to correct these violations, complete the certification at the end of this notice, and submit it to my attention. A follow-up inspection may be conducted to confirm completion of the corrective action. All violations must be corrected prior to the issuance of a Certificate of Operation. If you already have a Certificate of Operation, failure to correct these violations may result in the equipment being placed out of service and/or administrative fines under 35 P.S. §§ 1331.17-1331.18.

INDUSTRIAL BOARD PROCEDURE

ANY INDIVIDUAL AGGRIEVED BY THIS NOTICE MAY APPEAL TO THE PENNSYLVANIA INDUSTRIAL BOARD. AN INDIVIDUAL MAY ALSO MAKE A REQUEST FOR AN EXTENSION TO COMPLY WITH THIS NOTICE AND/OR REQUEST A VARIANCE FROM THE APPLICABLE REGULATIONS AND TECHNICAL STANDARDS. INDUSTRIAL BOARD FORMS ARE FOUND ON THE DEPARTMENT'S WEBSITE AT www.dli.pa.gov (KEY WORD: INDUSTRIAL BOARD FORMS). WHEN FILING AN APPEAL OR REQUEST WITH THE INDUSTRIAL BOARD, REFER TO THE FILE NUMBER FOUND ABOVE AND FULLY SET FORTH THE REASON FOR YOUR APPEAL, REQUEST FOR AN EXTENSION OF TIME, OR VARIANCE REQUEST. YOUR COMPLETED FORM MUST BE SENT TO: INDUSTRIAL BOARD, 651 BOAS STREET, ROOM 1622, HARRISBURG PENNSYLVANIA 17121 ALONG WITH PAYMENT.

For quickest resolution or questions, please first contact the inspector Austin Young at atyoung@travelers.com or Ph# 267-453-0170 with questions prior to contacting the main office.

Respectfully,

William J. Ross

Director Boiler Division

8509 on equipment 289285B have been corrected.	
All information provided on this certification is su unsworn falsification to authorities).	bject to the penalties of 18 Pa.C.S. § 4904 (relating to
Signature	Date

Please sign and return this completed statement using one of the following methods:

- 1. (preferred response method)Send an email with the signed letter attached to the original inspector atyoung@travelers.com.
- 2. (alternate response method) Send an email with the signed letter attached to the boilers division Boilers@pa.gov.
- 3. (alternate response method) Send the signed letter using traditional mail postal service to:

FINDING NO.1: The low water cutoff device installed on the boiler requires repair or replacement to ensure that it will interrupt the flow of fuel before the water level falls below the lowest safe permissible water level established by the boiler manufacturer. Replacement LWCO's shall conform to CSD-1. Ref: Act 85, 104, PA 34 3a.4, 3a.51, 3a.61, NBIC (Edit 342)

	v		
	in the second		



LINDY PROPERTY MANAGEMENT CO SUITE 211 309 YORK RD JENKINTOWN PA 19046

File No. 8509

Location: WARRINGTON CROSSINGS - J BUILDIN

1700 STREET RD

WARRINGTON PA 18976

RE: NOTICE OF VIOLATION

On 1/17/2025, Inspector Austin Young conducted an inspection at the above-referenced location on equipment 289286B and found violations of the Boiler Law(35 P.S. §§ 1331.1-1331.19) and the Law's regulations (34 Pa. Code §§ 3a.1-3a.171). These violations are attached to this letter.

You have 30 days to correct these violations, complete the certification at the end of this notice, and submit it to my attention. A follow-up inspection may be conducted to confirm completion of the corrective action. All violations must be corrected prior to the issuance of a Certificate of Operation. If you already have a Certificate of Operation, failure to correct these violations may result in the equipment being placed out of service and/or administrative fines under 35 P.S. §§ 1331.17-1331.18.

INDUSTRIAL BOARD PROCEDURE

ANY INDIVIDUAL AGGRIEVED BY THIS NOTICE MAY APPEAL TO THE PENNSYLVANIA INDUSTRIAL BOARD. AN INDIVIDUAL MAY ALSO MAKE A REQUEST FOR AN EXTENSION TO COMPLY WITH THIS NOTICE AND/OR REQUEST A VARIANCE FROM THE APPLICABLE REGULATIONS AND TECHNICAL STANDARDS. INDUSTRIAL BOARD FORMS ARE FOUND ON THE DEPARTMENT'S WEBSITE AT www.dli.pa.gov (KEY WORD: INDUSTRIAL BOARD FORMS). WHEN FILING AN APPEAL OR REQUEST WITH THE INDUSTRIAL BOARD, REFER TO THE FILE NUMBER FOUND ABOVE AND FULLY SET FORTH THE REASON FOR YOUR APPEAL, REQUEST FOR AN EXTENSION OF TIME, OR VARIANCE REQUEST. YOUR COMPLETED FORM MUST BE SENT TO: INDUSTRIAL BOARD, 651 BOAS STREET, ROOM 1622, HARRISBURG PENNSYLVANIA 17121 ALONG WITH PAYMENT.

For quickest resolution or questions, please first contact the inspector Austin Young at atyoung@travelers.com or Ph# 267-453-0170 with questions prior to contacting the main office.

Respectfully,

William J. Ross

Director Boiler Division

I hereby certify that all violations cited in the Notice of Violation dated January 21, 2025 for file number
8509 on equipment 289286B have been corrected.
All information provided on this certification is subject to the penalties of 18 Pa.C.S. § 4904 (relating to
unsworn falsification to authorities).

Signature	Date

Please sign and return this completed statement using one of the following methods:

- 1. (preferred response method)Send an email with the signed letter attached to the original inspector atyoung@travelers.com.
- 2. (alternate response method) Send an email with the signed letter attached to the boilers division Boilers@pa.gov.
- 3. (alternate response method) Send the signed letter using traditional mail postal service to:

FINDING NO.1: The low water cutoff device installed on the boiler requires repair or replacement to ensure that it will interrupt the flow of fuel before the water level falls below the lowest safe permissible water level established by the boiler manufacturer. Replacement LWCO's shall conform to CSD-1. Ref: Act 85, 104, PA 34 3a.4, 3a.51, 3a.61, NBIC (Edit 342)



LINDY PROPERTY MANAGEMENT CO SUITE 211 309 YORK RD JENKINTOWN PA 19046

File No. 8509

Location: WARRINGTON CROSSINGS - J BUILDIN

1700 STREET RD

WARRINGTON PA 18976

RE: NOTICE OF VIOLATION

On 1/17/2025, Inspector Austin Young conducted an inspection at the above-referenced location on equipment 364635B and found violations of the Boiler Law(35 P.S. §§ 1331.1-1331.19) and the Law's regulations (34 Pa. Code §§ 3a.1-3a.171). These violations are attached to this letter.

You have 30 days to correct these violations, complete the certification at the end of this notice, and submit it to my attention. A follow-up inspection may be conducted to confirm completion of the corrective action. All violations must be corrected prior to the issuance of a Certificate of Operation. If you already have a Certificate of Operation, failure to correct these violations may result in the equipment being placed out of service and/or administrative fines under 35 P.S. §§ 1331.17-1331.18.

INDUSTRIAL BOARD PROCEDURE

ANY INDIVIDUAL AGGRIEVED BY THIS NOTICE MAY APPEAL TO THE PENNSYLVANIA INDUSTRIAL BOARD. AN INDIVIDUAL MAY ALSO MAKE A REQUEST FOR AN EXTENSION TO COMPLY WITH THIS NOTICE AND/OR REQUEST A VARIANCE FROM THE APPLICABLE REGULATIONS AND TECHNICAL STANDARDS. INDUSTRIAL BOARD FORMS ARE FOUND ON THE DEPARTMENT'S WEBSITE AT www.dli.pa.gov (KEY WORD: INDUSTRIAL BOARD FORMS). WHEN FILING AN APPEAL OR REQUEST WITH THE INDUSTRIAL BOARD, REFER TO THE FILE NUMBER FOUND ABOVE AND FULLY SET FORTH THE REASON FOR YOUR APPEAL, REQUEST FOR AN EXTENSION OF TIME, OR VARIANCE REQUEST. YOUR COMPLETED FORM MUST BE SENT TO: INDUSTRIAL BOARD, 651 BOAS STREET, ROOM 1622, HARRISBURG PENNSYLVANIA 17121 ALONG WITH PAYMENT.

For quickest resolution or questions, please first contact the inspector Austin Young at atyoung@travelers.com or Ph# 267-453-0170 with questions prior to contacting the main office.

Respectfully,

William J. Ross

Director Boiler Division

8509 on equipment 364635B have been correct	ted.
All information provided on this certification is unsworn falsification to authorities).	s subject to the penalties of 18 Pa.C.S. § 4904 (relating to
G:	
Signature	Date

Please sign and return this completed statement using one of the following methods:

- 1. **(preferred response method)**Send an email *with the signed letter attached* to the original inspector atyoung@travelers.com.
- 2. (alternate response method) Send an email with the signed letter attached to the boilers division Boilers@pa.gov.
- 3. (alternate response method) Send the signed letter using traditional mail postal service to:

FINDING NO.1: Equip the boiler with a low water cutoff device (LWCO), designed for hot water service with a manual reset, which will automatically interrupt the flow of fuel to the boiler before the water level falls below the lowest safe permissible water level established by the boiler manufacturer. If the LWCO is connected to the boiler by piping or fittings, no isolation valves shall be placed between the LWCO and the boiler. A means shall be provided for testing the operation of the LWCO without resorting to draining the entire system. Such means shall not render the device inoperable. If the means temporarily isolates the device from the boiler during this testing, it shall automatically return to its normal position. Ref: Act 85, 104, PA 34 3a.4, 3a.51, 3a.61, CW-130 (c) (e) (Edit 341)





LINDY PROPERTY MANAGEMENT CO SUITE 211 309 YORK RD JENKINTOWN PA 19046

File No. 8509

Location: WARRINGTON CROSSINGS - J BUILDIN

1700 STREET RD

WARRINGTON PA 18976

RE: NOTICE OF VIOLATION

On 1/17/2025, Inspector Austin Young conducted an inspection at the above-referenced location on equipment 240758B and found violations of the Boiler Law(35 P.S. §§ 1331.1-1331.19) and the Law's regulations (34 Pa. Code §§ 3a.1-3a.171). These violations are attached to this letter.

You have 30 days to correct these violations, complete the certification at the end of this notice, and submit it to my attention. A follow-up inspection may be conducted to confirm completion of the corrective action. All violations must be corrected prior to the issuance of a Certificate of Operation. If you already have a Certificate of Operation, failure to correct these violations may result in the equipment being placed out of service and/or administrative fines under 35 P.S. §§ 1331.17-1331.18.

INDUSTRIAL BOARD PROCEDURE

ANY INDIVIDUAL AGGRIEVED BY THIS NOTICE MAY APPEAL TO THE PENNSYLVANIA INDUSTRIAL BOARD. AN INDIVIDUAL MAY ALSO MAKE A REQUEST FOR AN EXTENSION TO COMPLY WITH THIS NOTICE AND/OR REQUEST A VARIANCE FROM THE APPLICABLE REGULATIONS AND TECHNICAL STANDARDS. INDUSTRIAL BOARD FORMS ARE FOUND ON THE DEPARTMENT'S WEBSITE AT www.dli.pa.gov (KEY WORD: INDUSTRIAL BOARD FORMS). WHEN FILING AN APPEAL OR REQUEST WITH THE INDUSTRIAL BOARD, REFER TO THE FILE NUMBER FOUND ABOVE AND FULLY SET FORTH THE REASON FOR YOUR APPEAL, REQUEST FOR AN EXTENSION OF TIME, OR VARIANCE REQUEST. YOUR COMPLETED FORM MUST BE SENT TO: INDUSTRIAL BOARD, 651 BOAS STREET, ROOM 1622, HARRISBURG PENNSYLVANIA 17121 ALONG WITH PAYMENT.

For quickest resolution or questions, please first contact the inspector Austin Young at atyoung@travelers.com or Ph# 267-453-0170 with questions prior to contacting the main office.

Respectfully,

William J. Ross

Director Boiler Division

All information provided on this certification is sul unsworn falsification to authorities).	oject to the penalties of 18 Pa.C.S. § 4904 (relating to
Signature	Date

Please sign and return this completed statement using one of the following methods:

8509 on equipment 240758B have been corrected.

- 1. (preferred response method)Send an email with the signed letter attached to the original inspector atyoung@travelers.com.
- 2. (alternate response method) Send an email with the signed letter attached to the boilers division Boilers@pa.gov.
- 3. (alternate response method) Send the signed letter using traditional mail postal service to:

FINDING NO.1: The low water cutoff device installed on the boiler requires repair or replacement to ensure that it will interrupt the flow of fuel before the water level falls below the lowest safe permissible water level established by the boiler manufacturer. Replacement-LWCO's shall conform to CSD-1. Ref: Act 85, 104, PA 34 3a.4, 3a.51, 3a.61, NBIC (Edit 342)



LINDY PROPERTY MANAGEMENT CO SUITE 211 309 YORK RD JENKINTOWN PA 19046

File No. 8509

Location: WARRINGTON CROSSINGS - J BUILDIN

1700 STREET RD

WARRINGTON PA 18976

RE: NOTICE OF VIOLATION

On 1/17/2025, Inspector Austin Young conducted an inspection at the above-referenced location on equipment 240761B and found violations of the Boiler Law(35 P.S. §§ 1331.1-1331.19) and the Law's regulations (34 Pa. Code §§ 3a.1-3a.171). These violations are attached to this letter.

You have 30 days to correct these violations, complete the certification at the end of this notice, and submit it to my attention. A follow-up inspection may be conducted to confirm completion of the corrective action. All violations must be corrected prior to the issuance of a Certificate of Operation. If you already have a Certificate of Operation, failure to correct these violations may result in the equipment being placed out of service and/or administrative fines under 35 P.S. §§ 1331.17-1331.18.

INDUSTRIAL BOARD PROCEDURE

ANY INDIVIDUAL AGGRIEVED BY THIS NOTICE MAY APPEAL TO THE PENNSYLVANIA INDUSTRIAL BOARD. AN INDIVIDUAL MAY ALSO MAKE A REQUEST FOR AN EXTENSION TO COMPLY WITH THIS NOTICE AND/OR REQUEST A VARIANCE FROM THE APPLICABLE REGULATIONS AND TECHNICAL STANDARDS. INDUSTRIAL BOARD FORMS ARE FOUND ON THE DEPARTMENT'S WEBSITE AT www.dli.pa.gov (KEY WORD: INDUSTRIAL BOARD FORMS). WHEN FILING AN APPEAL OR REQUEST WITH THE INDUSTRIAL BOARD, REFER TO THE FILE NUMBER FOUND ABOVE AND FULLY SET FORTH THE REASON FOR YOUR APPEAL, REQUEST FOR AN EXTENSION OF TIME, OR VARIANCE REQUEST. YOUR COMPLETED FORM MUST BE SENT TO: INDUSTRIAL BOARD, 651 BOAS STREET, ROOM 1622, HARRISBURG PENNSYLVANIA 17121 ALONG WITH PAYMENT.

For quickest resolution or questions, please first contact the inspector Austin Young at atyoung@travelers.com or Ph# 267-453-0170 with questions prior to contacting the main office.

Respectfully,

William J. Ross

Director Boiler Division

All information provided on this certification is su unsworn falsification to authorities).	bject to the penalties of 18 Pa.C.S. § 4904 (relating to
Signature	Date

Please sign and return this completed statement using <u>one</u> of the following methods:

8509 on equipment 240761B have been corrected.

- 1. (preferred response method)Send an email with the signed letter attached to the original inspector atyoung@travelers.com.
- 2. (alternate response method) Send an email with the signed letter attached to the boilers division Boilers@pa.gov.
- 3. (alternate response method) Send the signed letter using traditional mail postal service to:

FINDING NO.1: The low water cutoff device installed on the boiler requires repair or replacement to ensure that it will interrupt the flow of fuel before the water level falls below the lowest safe permissible water level established by the boiler manufacturer. Replacement LWCO's shall conform to CSD-1. Ref: Act 85, 104, PA 34 3a.4, 3a.51, 3a.61, NBIC (Edit 342)