

Due Diligence Audit -: 02-09-2021

Technician	Alison Snyder		
Property	540 West Sedgwick Street		
Unit	С3		
Floorplan	2 Bed 1 Bath		
Occupied?	No		
Keys Worked?	No		
Audit Date	03-02-2021		
Unit Condition	Good		
Resident House Keeping	Good		
Comments			

Amenity Name	Amenity Description	Amenity Code	Amenity Price	Exists
Washer & Dryer in Unit	Washer & Dryer in Unit	Washer & Dryer in Un	\$100	No
White Kitchen	White Kitchen	White Kitchen	\$175	Yes
Updated Appliance Pkg	Updated Appliance Pkg	Updated Appliance Pk	\$50	No
Bathroom Upgrade	Bathroom Upgrade	Bathroom Upgrade	\$50	Yes
Quartz Countertops	Quartz Countertops	Quartz Countertops	\$25	Yes
Granite Countertops	Granite Countertops	Granite Countertops	\$25	No
Classic Kitchen	Classic Kitchen	Classic Kitchen	\$0	No
Classic Bathroom	Classic Bathroom	Classic Bathroom	\$0	No
Private Entrance	Private Entrance	Private Entrance	\$25	No
Plank Flooring	Plank Flooring	Plank Flooring	\$0	No
Parquet Flooring	Parquet Flooring	Parquet Flooring	\$0	Yes



