



Date of Incident	06-14-2024
Prepared By	Andrea Reusser
Property	Rosedale Court
Time of Incident	03:00:00
Location of Incident	Trash corral between A and B building

Incident Type
Vendor Activity
Incident Type Category
Damage to Property
Description of Incident
Amazon driver in rented U-Haul Van backed into and along the side of, the trash corral busting out a panel, bending several posts.
Corrective action taken at the time of the incident
Nothing, incident discovered at end of day.
What we have done related to Customer Service and helping the resident, if anything?
Pieces were removed and disposed of to avoid additional damage or injury
Witnesses names and phone number
None.
Was there security camera footage of this incident?
Yes
Link to security footage video in Box
https://lindyproperties.box.com/s/e1jc6p71qxhb6yale9b5kmgtp1g93h2r
Did this incident involve a resident?
No
Did this incident involve a Lindy team member?
No
Did this incident involve a vendor?
Yes
Vendor Name
Amazon Contract Delivery Driver
Should this incident be reported to the residents renters insurance policy?
No
View Video

