

Maintenance Request Added On : 01-08-2024

See Attached Photo for More Detail

Category	Painting
SubCategory	Other
Other Description	Paint behind table
Property	York North (YONO)
Reported by	Shawn Hargett
Issue Note	Paint behind table, near elevator

