

## Maintenance Request Added On : 01-10-2025

See Attached Photo for More Detail

<b>Category</b>	<b>Plumbing</b>
<b>SubCategory</b>	<b>Other</b>
<b>Other Description</b>	<b>leak</b>
<b>Property</b>	<b>Westgate Arms</b>
<b>Reported by</b>	<b>Jeff Wilson</b>
<b>Issue Note</b>	<b>Fitness center ceiling leak</b>

