

## Maintenance Request Added On : 01-15-2024

See Attached Photo for More Detail

<b>Category</b>	<b>Make Ready</b>
<b>SubCategory</b>	<b>PM final walk through</b>
<b>Property</b>	<b>Elkins Park Terrace</b>
<b>Reported by</b>	<b>Andrea Reusser</b>
<b>Issue Note</b>	<b>Remove tape and reattach necessary tub hardware after glazing. Both bathrooms</b>

