

Maintenance Request Added On : 01-26-2024

See Attached Photo for More Detail

Category	Electrical
SubCategory	Other
Other Description	feed to 625 jacket worn
Property	201-207 Leedom St.
Reported by	Frank Lindy
Issue Note	Jacket to electrical feed needs replacement

