

Maintenance Request Added On : 03-07-2025

See Attached Photo for More Detail

| | |
|--------------------|--|
| Category | Preventative Maint |
| SubCategory | Parking Lot |
| Property | Towers at Wyncote |
| Reported by | Frank Lindy |
| Issue Note | Lid for drain line next to kalos office bldng 1 lobby |

