

Maintenance Request Added On : 03-10-2026

See Attached Photo for More Detail

Category	Carpentry
SubCategory	Other
Other Description	Main parking lot guard rail post fence
Property	The Diamond at Phoenixville
Reported by	Thomas Hines
Issue Note	Broken off wood guard rail post fence in main parking lot area .

