

## Maintenance Request Added On : 03-18-2024

See Attached Photo for More Detail

<b>Category</b>	<b>Plumbing</b>
<b>SubCategory</b>	<b>Kitchen Sink</b>
<b>Property</b>	<b>York North (YONO)</b>
<b>Reported by</b>	<b>Shawn Hargett</b>
<b>Issue Note</b>	<b>Leak coming from basket</b>

