

## Maintenance Request Added On : 04-04-2024

See Attached Photo for More Detail

<b>Category</b>	<b>Common Area</b>
<b>SubCategory</b>	<b>Other</b>
<b>Other Description</b>	<b>leasing office</b>
<b>Property</b>	<b>York North (YONO)</b>
<b>Reported by</b>	<b>Jacquelyn Owens</b>
<b>Issue Note</b>	<b>Leak in ceiling near Jack's desk</b>

