

## Maintenance Request Added On : 04-23-2025

See Attached Photo for More Detail

<b>Category</b>	<b>Electrical</b>
<b>SubCategory</b>	<b>Other</b>
<b>Other Description</b>	<b>Wire exposed exterior</b>
<b>Property</b>	<b>Rosedale Court</b>
<b>Reported by</b>	<b>Thomas Hines</b>
<b>Issue Note</b>	<b>Exposed exterior wire , with cuts on it. Possibly leading to lamp post in front; along area of E-Building walkway.</b>

