

$Maintenance\ Request\ Added\ On: 04\text{-}28\text{-}2025$

See Attached Photo for More Detail

Category	Electrical
SubCategory	Other
Other Description	Electrical junction Box
Property	Joshua House
Reported by	Thomas Hines
Issue Note	(Building: C-East) Electrical wires exposed , with bird nest exposed. Maybe phone wires . A cover is needed.

