

## Maintenance Request Added On : 04-28-2025

See Attached Photo for More Detail

<b>Category</b>	<b>Electrical</b>
<b>SubCategory</b>	<b>Other</b>
<b>Other Description</b>	<b>Electrical junction Box</b>
<b>Property</b>	<b>Joshua House</b>
<b>Reported by</b>	<b>Thomas Hines</b>
<b>Issue Note</b>	<b>(Building: C-East) Electrical wires exposed , with bird nest exposed. Maybe phone wires . A cover is needed. On side of building, with fence.</b>

