

Maintenance Request Added On : 04-28-2025

See Attached Photo for More Detail

Category	Electrical
SubCategory	Other
Other Description	Exterior Electrical Box
Property	Joshua House
Reported by	Thomas Hines
Issue Note	(Building E-South); across from rear D-East....Wires exposed. Box cover needs to be installed.

