

Maintenance Request Added On : 04-28-2025

See Attached Photo for More Detail

| | |
|--------------------------|---|
| Category | Electrical |
| SubCategory | Other |
| Other Description | Exterior Electrical Box |
| Property | Joshua House |
| Reported by | Thomas Hines |
| Issue Note | (Building E-South); across from rear D-East....Wires exposed. Box cover needs to be installed. |

