

Maintenance Request Added On : 04-28-2025

See Attached Photo for More Detail

Category	Carpentry
SubCategory	Doors
Property	Joshua House
Reported by	Thomas Hines
Issue Note	(Building L-South / Rear)...please seal and install door trim.

