

Maintenance Request Added On : 05-17-2023

See Attached Photo for More Detail

Category	Common Area
SubCategory	Fitness center
Property	York North (YONO)
Reported by	Amber Johnson
Issue Note	Replace brown drop ceiling, fix gym ac

