

Maintenance Request Added On: 06-04-2025

See Attached Photo for More Detail

Category	Security
SubCategory	Other
Other Description	Unattended unlocked outside basement door.
Property	Warrington Crossings
Reported by	Thomas Hines
Issue Note	Outside basement is unlocked and viewed open with no one working? Security issue. In back of building 'J' .



