

## Maintenance Request Added On : 06-06-2023

See Attached Photo for More Detail

<b>Category</b>	<b>Windows</b>
<b>SubCategory</b>	<b>Broken</b>
<b>Property</b>	<b>450 Green Apartments</b>
<b>Reported by</b>	<b>Jeff Wilson</b>
<b>Issue Note</b>	<b>E202 broken glass window</b>

