

Maintenance Request Added On : 11-04-2025

See Attached Photo for More Detail

Category	Other
SubCategory	Other
Other Description	Exterior stairway/ Mechanical Room entrance
Property	Willow Bend
Reported by	Thomas Hines
Issue Note	C- Building/ Side Stairway / Mechanical Room entrance blocked by bags of solid concrete mix and pole signs . Please remove. Thank you.

