

## Maintenance Request Added On: 12-08-2023

## See Attached Photo for More Detail

Category	Make Ready
SubCategory	Unit Inspection
Property	Overlook Apartments
Reported by	Andrea Reusser
Issue Note	Repair wall next to toilet paper holder in bathroom

