

## Maintenance Request Added On : 12-13-2023

See Attached Photo for More Detail

<b>Category</b>	<b>Security</b>
<b>SubCategory</b>	<b>Other</b>
<b>Other Description</b>	<b>door</b>
<b>Property</b>	<b>Overlook Apartments</b>
<b>Reported by</b>	<b>Andrea Reusser</b>
<b>Issue Note</b>	<b>Replace adhock strike plate Put cover plate back on to prevent breaking in Back door 1573</b>

