

Maintainence Request Added On : 12-14-2022

Category	Common Area
SubCategory	Laundry Room
Property	Joshua House
Reported by	Nancy Benner
Issue Note	Drain filled with dirt and lint and cover rusted buckled and broken -lint and debris on floor and exposed mouse traps in view

