

## **Move Out Inventory & Condition Form**

<b>Inspection Date</b>	Technician	Property	Units
01-31-2024	Dawn Buck	Bromley House	B113

Approved By	Auto Approved
Resident Name	Kasia Duckett
Forwarding Mailing Address	6344 N 8th Street Apt 108 Philadelphia, PA 19126
Date Resident Turned in Keys	01-30-2024

Damage Summary				
Main Category Sub Category Charges Type Note Charges				Charges
Additional Damage Charges				
Total Charges		\$0.00		

	Amenities to be added to this Unit
Quartz Countertops	
White Mod Kitchen 1	

LIVING ROOM:	
Ceilings / Lights:	Ok
Door / Closet:	Ok
Other:	Ok
Walls / Outlets:	Ok
Window:	Ok
Window coverings:	Ok

DINING ROOM:	
Ceilings / Lights:	N/A
Walls / Outlets:	N/A
Window:	N/A

Window coverings:	N/A	
KITCHEN:		
Backsplash:		О
Cabinets:		
Cabinet Door:	Ok	
Cabinets:		
Cabinet Handle:	Ok	
Cabinets:		
Cabinet Shelf:	Ok	
Ceiling Fan:		N
Ceiling Light Fixture:		0
Ceiling Lights:		0
Cleaning of Stove:		О
Counter Top:		О
Dishwasher:		
Dishwasher Knob:	N/A	
Dishwasher:		
Dishwasher Rack:	N/A	
Dishwasher:		
Dishwasher Silverware Holder:		N/A
Drip Pan:		0
Electric Meter:		0
Faucet:		О
Faucet Knobs:		0
Floors:		0
Formica/Tiles:		0
Garbage Disposal:		0
Kitchen Sink:		0
Microwave:		N
Other:		N

Oven / Range:			
Oven Cleaning:		Ok	
Oven / Range:			
Oven door handle:		Ok	
Oven / Range:			
Oven drip pan:	(	Ok	
Oven / Range:			
Oven knobs:	0	k	
Oven / Range:			
Oven Racks:	0	k	
Oven / Range:			
Range burners:	(	Ok	
Oven / Range:			
Range Hood:	0	k	
Oven Door Handle:			0
Oven Racks:			0
Range Top:			0
Refrigerator (Freezer):			
Cleaning Refrigerator:		Ok	
Refrigerator (Freezer):			
Refrigerator (Drawers):		Ok	
Refrigerator (Freezer):			
Refrigerator (Shelf and Bars):		Ok	
Refrigerator (Freezer):			
Refrigerator Crisper Glass/Plastic:		Ok	
Rubber Stopper:			0
Stove Knob:			0
Verify that either a Fire Stop (under the microwave) or FireAver	t (behind the stove) exists.:		O]

Wall Outlets:	Ok
Washer/Dryer:	N/A
Window Coverings:	N/A

BEDROOMS:	
Ceilings / Lights:	N/A
Door / Closet:	N/A
Floors / Carpet:	N/A
Other:	N/A
Walls / Outlets:	N/A
Window:	N/A
Window coverings:	N/A

BATHROOM:	
Cabinets / Mirror:	Ok
Ceiling Lights:	Ok
Cleaning Bathroom:	Ok
Complete Toilet:	Ok
Counter Top:	Ok
Floors:	Ok
Formica /Tile:	Ok
Is there signs of moisture from outside in the apartment?:	Ok
Medicine Cabinet:	Ok
Mirror Cabinet:	Ok
Other:	Ok
Remove Mildew on Tiles:	Ok
Shower Curtain Bar:	Ok
Shower Head:	Ok
Sink:	Ok
Soad Dish (Tub):	Ok
Soap Dish (Sink):	Ok
Toilet Paper Holder:	Ok
Toilet Tank:	Ok
Towel Bar:	Ok

Tub Knob(s):	Ok
Tub Reglazing:	Ok
Vanity Cabinet:	Ok
Wall Outlets:	Ok
Window:	Ok

LOCKS:	
Door Knob:	Ok
Door Lock:	Ok
Ensure the apartment door has an automatic closure and closes properly. :	Ok
Fix Door when extra lock is removed:	Ok
Mail-Box Lock:	Ok

KEYS:	
Failure To Return Apartment Key:	Ok
Failure To Return Mailbox Key:	Ok

DOORS:	
Apartment Door:	Ok
Apartment Door closes automatically:	Ok
Frame:	Ok
Hollow:	Ok
Solid Core & Steel:	Ok

PAINTING:	
Border Removal (Per Room):	Ok
Holes in Walls (Each Hole):	Ok
Over Dark Colors (Per Room):	Ok
Wallpaper Removal (Per Room):	Ok

CARPET:	
Burns:	Ok
Deodorize:	Ok
Pet Treatment (Odor):	Ok
Replace Carpet 1 Bedroom:	Ok
Replace Carpet 2 Bedroom:	Ok

Shampoo 1 Bedroom:	Ok
Shampoo 2 Bedroom:	Ok
Stain Removal:	Ok

MICORIA ANTRONIO	
MISCELLANEOUS:	
Broken Window Glass (Per Pane):	Ok
Cabinet Equipment:	Ok
Carbon Monoxide Detector:	Ok
Cleaning of Apartment:	Ok
Clear Storage Locker:	Ok
Closet Shelves:	Ok
Common Area damaged during moveout:	Ok
Door Intercom System:	Ok
Exhaust Fan:	Ok
Fan Blades:	Ok
If fire stops have been installed throughout the property, ensure fire stops are installed.:	Ok
Date of Installation	2022-01-3
Light Globes:	Ok
Mini Blind(s) each:	Ok
Outside Lights:	Ok
Phone Jack:	Ok
Rallings:	Ok
Removal Of Bulk Items:	Ok
Remove Debris (Per Bag):	Ok
Sliding Mirror/Glass Door (2):	Ok
Smoke Detector Alarm:	Ok
Stoppage by foreign object in any drain:	Ok
Switch Plate Covers:	Ok
Thermostat Cover:	Ok
Vertical Blinds:	Ok
Vinly Tile Bathroom:	Ok
Vinly Tile Kitchen:	Ok
Was personal property left behind?:	Yes


Estimated Value of Personal Property is.	\$0	
Window Screen(s) each:		Ok
Window Sills:		Ok

OVERALL:	
Signs of Moisture inside the apartment:	Ok
Signs of Moisture outside the apartment:	Ok

Resident
----------

Lindv	Community	Representative	Name
	00111111111111111	Ttoprocomount.	- 102220

Dawn Buck



Technician	Dawn Buck
Resident not available for signature	YES