

## **Make Ready Checklist Inspection**

Inspection Date	Technician	Property	Units
02-11-2023	Travis Poston	Towers at Wyncote	1221-3

LIVING ROOM:	
Ceilings / Lights:	Ok
Door / Closet:	Ok
Other:	Ok
Plank Flooring:	Ok
Walls / Outlets:	Ok
Window:	Ok
Window coverings:	Ok

DINING ROOM:	
Ceilings / Lights:	Ok
Plank Flooring:	Ok
Walls / Outlets:	Ok
Window:	Ok
Window coverings:	Ok

KITCHEN:	
Backsplash:	
Cabinets:	
Cabinet Door:	Ok
Cabinets:	
Cabinet Handle:	Ok

Cabinets:	
Cabinet Shelf:	Ok

Ceiling Fan: Ceiling Light Fixture:		Ok	
Ceiling Lights:		Ok	
Cleaning of Stove:		Ok	
Counter Top:		Ok	
Dishwasher:			
Dishwasher Knob: Ok			
Dishwasher:			
Dishwasher Rack:	Ok		
Dishwasher:			
Dishwasher Silverware Holder:		Ok	
Drip Pan:		Ok	
Electric Meter:		Ok	
Faucet:		Ok	
Faucet Knobs:		Ok	
Floors:		Ok	
Formica/Tiles:		Ok	
Garbage Disposal:		Ok	
Kitchen Sink:		Ok	
Microwave:		Ok	
Other:		Ok	
Oven / Range:			
Oven Cleaning:	Ok		
Oven / Range:			
Oven door handle:	Ol	ζ	
Oven / Range:			
Oven drip pan:	Ok		
Oven / Range:			
Oven knobs:	Ok		

Oven / Range:			
Oven Racks:	Ok		
Oven / Range:			
Range burners:	0	k	
Oven / Range:			
Range Hood:	Ok		
Oven Door Handle:			Ok
Oven Racks:			Ok
Range Top:			Ok
Refrigerator (Fre	ezer):		
Cleaning Refrigera	tor:	Ok	
Refrigerator (Fre	ezer):		
Refrigerator (Drawers):  Ok			
Refrigerator (Fre	ezer):		
Refrigerator (Shelf and Bars):  Ok			
Refrigerator (Fre	ezer):		
Refrigerator Crisper Glass/Plastic: Ok			k
Rubber Stopper:			Ok
Stove Knob:			Ok
Verify that either a Fire Stop (under the microwave) or FireAvert (behind the stove) exists.:		Ok	
Wall Outlets:			Ok
Washer/Dryer:		Ok	
Window Coverings:		Ok	
BEDROOMS:			
Ceilings / Lights:	Ok		

Door / Closet:

Floors / Carpet:

Charges Type

Charges

Ok

0

Not Ok

_	•								
(	0	n	n	J.	n	า	Φ.	n	t

Impressions in the carpet from previous furniture but not ok bad.  $\,$ 



Other:	Ok
Plank Flooring:	N/A
Walls / Outlets:	Ok
Window:	Ok
Window coverings:	Ok

BATHROOM:	
Cabinets / Mirror:	Ok
Ceiling Lights:	Not Ok
Charges Type	
Charges	0
Comment	Light over vanity in bathroom is crooked/ hanging.  Look to be missing a bolt/ screw to connect to wall.



Cleaning Bathroom:	Ok
Complete Toilet:	Ok
Counter Top:	Ok
Floors:	Ok
Formica /Tile:	Ok
Is there signs of moisture from outside in the apartment?:	Ok

Medicine Cabinet:	Ok
Mirror Cabinet:	Ok
Other:	Ok
Plank Flooring:	Ok
Remove Mildew on Tiles:	Ok
Shower Curtain Bar:	Ok
Shower Head:	Ok
Sink:	Ok
Soad Dish (Tub):	Ok
Soap Dish (Sink):	Ok
Toilet Paper Holder:	Ok
Toilet Tank:	Ok
Towel Bar:	Ok
Tub Knob(s):	Ok
Tub Reglazing:	Ok
Vanity Cabinet:	Ok
Wall Outlets:	Ok
Window:	Ok

LOCKS:	
Door Knob:	Ok
Door Lock:	Ok
Ensure the apartment door has an automatic closure and closes properly. :	Ok
Fix Door when extra lock is removed:	Ok
Mail-Box Lock:	Ok

KEYS:		
Failure To Return Apartment Key:	Ok	
Failure To Return Mailbox Key:	Ok	

DOORS:	
Apartment Door:	Ok
Apartment Door closes automatically:	Ok
Frame:	Ok
Hollow:	Ok

Solid Core & Steel:	Ok
---------------------	----

PAINTING:	
Border Removal (Per Room):	Ok
Holes in Walls (Each Hole):	Ok
Over Dark Colors (Per Room):	Ok
Wallpaper Removal (Per Room):	Ok

CARPET:	
Burns:	Ok
Deodorize:	Ok
Pet Treatment (Odor):	Ok
Replace Carpet 1 Bedroom:	Ok
Replace Carpet 2 Bedroom:	Ok
Shampoo 1 Bedroom:	Ok
Shampoo 2 Bedroom:	Ok
Stain Removal:	Ok

MISCELLANEOUS:	
Broken Window Glass (Per Pane):	Ok
Cabinet Equipment:	Ok
Carbon Monoxide Detector:	Ok
Cleaning of Apartment:	Ok
Clear Storage Locker:	Ok
Closet Shelves:	Ok
Common Area damaged during moveout:	Ok
Confirm you have installed or there is in place a stainless steel toilet tank water connector.:	Ok
Door Intercom System:	Ok
Exhaust Fan:	Not Ok
Charges Type	
Charges	0
Comment	Central air vent looks to have large amount of dust or very dirty filter. Please clean/ replace.



Fan Blades:	Ok
Fire extinguisher:	Ok
If fire stops have been installed throughout the property, ensure fire stops are installed.:	Ok
Light Globes:	Ok
Mini Blind(s) each:	Ok
Outside Lights:	Ok
Phone Jack:	Ok
Rallings:	Ok
Removal Of Bulk Items:	Ok
Remove Debris (Per Bag):	Ok
Sliding Mirror/Glass Door (2):	Ok
Smoke Detector Alarm:	Ok
Stoppage by foreign object in any drain:	Ok
Switch Plate Covers:	Ok
Thermostat Cover:	Ok
Vertical Blinds:	Ok
Vinly Tile Bathroom:	Ok
Vinly Tile Kitchen:	Ok
Window Screen(s) each:	Ok
Window Sills:	Ok

OVERALL:	
Signs of Moisture inside the apartment:	Ok
Signs of Moisture outside the apartment:	Ok

Resident	Travis Poston
Resident	114113 1 031011



Lindy Community Representative Name	Travis Poston
Jun full	

Technician	Travis Poston
Resident not available for signature	