



Make Ready Checklist Inspection

Inspection Date	Technician	Property	Units
02-26-2021	Silvana Pinargote	Meadowbrook	871

LIVING ROOM:	
Walls / Outlets:	Ok
Ceilings / Lights:	Ok
Window:	Ok
Door / Closet:	Ok
Window coverings:	Ok
Other:	Ok
DINING ROOM:	
Walls / Outlets:	Ok
Ceilings / Lights:	Ok
Window:	Ok
Window coverings:	Ok
KITCHEN:	
Cabinets:	Ok
Cabinet Door:	Ok
Cabinet Shelf:	Not Ok
Charges Type	
Charges	0



Counter Top:	Not Ok
Charges Type	
Charges	0



Refrigerator (Freezer):	Ok
Refrigerator (Shelf and Bars):	Ok
Refrigerator (Drawers):	Ok
Refrigerator Crisper Glass/Plastic:	Ok
Cleaning Refrigerator:	Ok
Dishwasher Rack:	Ok
Dishwasher Silverware Holder:	Ok
Dishwasher Knob:	Ok
Fire Stops:	Ok
Formica/Tiles:	Ok
Stove Knob:	Ok
Microwave:	Ok
Cleaning of Stove:	Ok
Ceiling Lights:	Ok
Garbage Disposal:	Ok
Rubber Stopper:	Not Ok


Charges Type	
Charges	0
Comment	Rubber stopper missing
Oven Door Handle:	Ok
Oven Racks:	Ok
Kitchen Sink:	Ok
Faucet Knobs:	Ok
Floors:	Ok
Faucet:	Ok
Drip Pan:	Ok
Range Hood:	Ok
Range Top:	Not Ok
Charges Type	
Charges	0



Ceiling Light Fixture:	Ok
Backsplash:	Ok
Ceiling Fan:	Ok
Washer/Dryer:	Ok
Wall Outlets:	Ok
Window Coverings:	Ok
CARPET:	
Stain Removal:	Not Ok
Charges Type	
Charges	0



Burns:	Not Ok
Charges Type	
Charges	0
Comment	Burn marks by mirror closet in BR, stains in living room/dining room area



Deodorize:	Not Ok
Charges Type	
Charges	0
Comment	Strong smoke smell in apt, smell is stronger in bathroom
Resident	

Lindy Community Representative Name	Silvana Pinargote
	
Technician	Silvana Pinargote
Resident not available for signature	
Resident refused Signature	