



Make Ready Checklist Inspection

| Inspection Date | Technician | Property | Units |
|-----------------|-------------------|-------------|-------|
| 02-26-2021 | Silvana Pinargote | Meadowbrook | 871 |

| | |
|---------------------|--------|
| LIVING ROOM: | |
| Walls / Outlets: | Ok |
| Ceilings / Lights: | Ok |
| Window: | Ok |
| Door / Closet: | Ok |
| Window coverings: | Ok |
| Other: | Ok |
| DINING ROOM: | |
| Walls / Outlets: | Ok |
| Ceilings / Lights: | Ok |
| Window: | Ok |
| Window coverings: | Ok |
| KITCHEN: | |
| Cabinets: | Ok |
| Cabinet Door: | Ok |
| Cabinet Shelf: | Not Ok |
| Charges Type | |
| Charges | 0 |



| | |
|--------------|--------|
| Counter Top: | Not Ok |
| Charges Type | |
| Charges | 0 |



| | |
|-------------------------------------|--------|
| Refrigerator (Freezer): | Ok |
| Refrigerator (Shelf and Bars): | Ok |
| Refrigerator (Drawers): | Ok |
| Refrigerator Crisper Glass/Plastic: | Ok |
| Cleaning Refrigerator: | Ok |
| Dishwasher Rack: | Ok |
| Dishwasher Silverware Holder: | Ok |
| Dishwasher Knob: | Ok |
| Fire Stops: | Ok |
| Formica/Tiles: | Ok |
| Stove Knob: | Ok |
| Microwave: | Ok |
| Cleaning of Stove: | Ok |
| Ceiling Lights: | Ok |
| Garbage Disposal: | Ok |
| Rubber Stopper: | Not Ok |


| | |
|-------------------|------------------------|
| Charges Type | |
| Charges | 0 |
| Comment | Rubber stopper missing |
| Oven Door Handle: | Ok |
| Oven Racks: | Ok |
| Kitchen Sink: | Ok |
| Faucet Knobs: | Ok |
| Floors: | Ok |
| Faucet: | Ok |
| Drip Pan: | Ok |
| Range Hood: | Ok |
| Range Top: | Not Ok |
| Charges Type | |
| Charges | 0 |




| | |
|------------------------|--------|
| Ceiling Light Fixture: | Ok |
| Backsplash: | Ok |
| Ceiling Fan: | Ok |
| Washer/Dryer: | Ok |
| Wall Outlets: | Ok |
| Window Coverings: | Ok |
| CARPET: | |
| Stain Removal: | Not Ok |
| Charges Type | |
| Charges | 0 |



| | |
|--------------|---|
| Burns: | Not Ok |
| Charges Type | |
| Charges | 0 |
| Comment | Burn marks by mirror closet in BR, stains in living room/dining room area |



| | |
|--------------|--|
| Deodorize: | Not Ok |
| Charges Type | |
| Charges | 0 |
| Comment | Strong smoke smell in apt, smell is stronger in bathroom |
| Resident | |

| | |
|---|-------------------|
| Lindy Community Representative Name | Silvana Pinargote |
|  | |
| Technician | Silvana Pinargote |
| Resident not available for signature | |
| Resident refused Signature | |