

Move Out Inventory & Condition Form

Inspection Date	Technician	Property	Units
02-27-2025	Nilsa Reyes	Joshua House	G0302

Approved By	Nilsa Reyes
Resident Name	Christopher Polanco
Forwarding Mailing Address	98 Scott Run Court Bear, DE 19701
Date Resident Turned in Keys (For evictions - date all belongings were removed)	02-23-2025

Damage Summary				
Main Category	Sub Category	Charges Type	Note	Charges
MISCELLANEOUS	Was personal property left behind?			\$0
MISCELLANEOUS	Was the resident locked out?			\$0
Additional Damage Charges				
Total Charges		\$0.00		

LIVING ROOM:	
Ceilings / Lights:	Ok
Door / Closet:	Ok
Other:	Ok
Walls / Outlets:	Ok
Window:	Ok
Window coverings:	Ok

DINING ROOM:	
Ceilings / Lights:	Ok
Walls / Outlets:	Ok
Window:	Ok

Window coverings:		Ok		
KITCHEN:				
Backsplash:				Ok
Cabinets:				
Cabinet Door:	(Ok		
Cabinets:				
Cabinet Handle:		Ok		
Cabinets:				
Cabinet Shelf:	(Ok		
Ceiling Fan:				Ok
Ceiling Light Fixture:				Ok
Ceiling Lights:				Ok
Cleaning of Stove:				Ok
Counter Top:				Ok
Dishwasher:				
Dishwasher Knob:		Ok		
Dishwasher:				
Dishwasher Rack:		Ok		
Dishwasher:				
Dishwasher Silverware Holder:			Ok	
Drip Pan:				Ok
Electric Meter:				Ok
Faucet:				Ok
Faucet Knobs:				Ok
Floors:				Ok
Formica/Tiles:				Ok
Garbage Disposal:				Ok
Kitchen Sink:				Ok
Microwave:				Ok
Other:				Ok

Oven / Range:		
Oven Cleaning:		Ok
Oven / Range:		
Oven door handle:		Ok
Oven / Range:		
Oven drip pan:		Ok
Oven / Range:		
Oven knobs:		Ok
Oven / Range:		
Oven Racks:		Ok
Oven / Range:		
Range burners:		Ok
Oven / Range:		
Range Hood:		Ok
Oven Door Handle:		(
Oven Racks:		(
Range Top:		(
Refrigerator (Freezer):		(
Rubber Stopper:		(
Stove Knob:		(
Verify that either a Fire Stop (under the microwave) or FireAvert (behind the stove) exists.:		:
Vall Outlets:		(
Vasher/Dryer:		(
Vindow Coverings:		(
BEDROOMS:		

BEDROOMS:	
Ceilings / Lights:	Ok
Door / Closet:	Ok
Floors / Carpet:	Ok
Other:	Ok

Walls / Outlets:	Ok
Window:	Ok
Window coverings:	Ok

BATHROOM:	
Cabinets / Mirror:	Ok
Ceiling Lights:	Ok
Cleaning Bathroom:	Ok
Complete Toilet:	Ok
Counter Top:	Ok
Floors:	Ok
Formica /Tile:	Ok
Is there signs of moisture from outside in the apartment?:	Ok
Medicine Cabinet:	Ok
Mirror Cabinet:	Ok
Other:	Ok
Remove Mildew on Tiles:	Ok
Shower Curtain Bar:	Ok
Shower Head:	Ok
Sink:	Ok
Soad Dish (Tub):	Ok
Soap Dish (Sink):	Ok
Toilet Paper Holder:	Ok
Toilet Tank:	Ok
Towel Bar:	Ok
Tub Knob(s):	Ok
Tub Reglazing:	Ok
Vanity Cabinet:	Ok
Wall Outlets:	Ok
Window:	Ok

LOCKS:	
Door Knob:	Ok
Door Lock:	Ok

Ensure the apartment door has an automatic closure and closes properly. :	Ok
Fix Door when extra lock is removed:	Ok
Mail-Box Lock:	Ok

KEYS:	
Failure To Return Apartment Key:	Ok
Failure To Return Mailbox Key:	Ok

DOORS:	
Apartment Door:	Ok
Apartment Door closes automatically:	Ok
Frame:	Ok
Hollow:	Ok
Solid Core & Steel:	Ok

PAINTING:	
Border Removal (Per Room):	Ok
Holes in Walls (Each Hole):	Ok
Over Dark Colors (Per Room):	Ok
Wallpaper Removal (Per Room):	Ok

CARPET:	
Burns:	Ok
Deodorize:	Ok
Pet Treatment (Odor):	Ok
Replace Carpet 1 Bedroom:	Ok
Replace Carpet 2 Bedroom:	Ok
Shampoo 1 Bedroom:	Ok
Shampoo 2 Bedroom:	Ok
Stain Removal:	Ok

MISCELLANEOUS:	
Broken Window Glass (Per Pane):	Ok
Cabinet Equipment:	Ok
Carbon Monoxide Detector:	Ok
Cleaning of Apartment:	Ok

Clear Storage Locker:	Ok
Closet Shelves:	Ok
Common Area damaged during moveout:	Ok
Door Intercom System:	Ok
Exhaust Fan:	Ok
Fan Blades:	Ok
If fire stops have been installed throughout the property, ensure fire stops are installed.:	Ok
Light Globes:	Ok
Mini Blind(s) each:	Ok
Outside Lights:	Ok
Phone Jack:	Ok
Rallings:	Ok
Removal Of Bulk Items:	Ok
Remove Debris (Per Bag):	Ok
Sliding Mirror/Glass Door (2):	Ok
Smoke Detector Alarm:	Ok
Stoppage by foreign object in any drain:	Ok
Switch Plate Covers:	Ok
Thermostat Cover:	Ok
Vertical Blinds:	Ok
Vinly Tile Bathroom:	Ok
Vinly Tile Kitchen:	Ok
Was personal property left behind?:	No
Charges Type	
Charges	0
Was the resident locked out?:	Not Ol
Charges Type	
Charges	0
Window Screen(s) each:	Ok
Window Sills:	Ok

OVERALL:	
Signs of Moisture inside the apartment:	Ok
Signs of Moisture outside the apartment:	Ok

Resident	
Lindy Community Representative Name	Nilsa Reyes
Technician	Nilsa Reyes
Resident not available for signature	YES