




## Make Ready Checklist Inspection


Inspection Date	Technician	Property	Units
04-13-2020	Marva Brown	Gateway Towers	C212

BATHROOM:	
Sink:	Not Ok
Charges Type	
Charges	0
Comment	Burns on sink



MISCELLANEOUS:	
Smoke Detector Alarm:	Not Ok
Charges Type	
Charges	0
Comment	Smoke detector missing



Resident	vacant
	
Lindy Community Representative Name	Marva Brown
	
Technician	Marva Brown
Resident not available for signature	
Resident refused Signature	