

Move Out Inventory & Condition Form

Inspection Date	Technician	Property	Units
05-01-2020	Rafael Soto Ocasio	Meadowbrook	337

Resident Name	Estate of
Forwarding Mailing Address	Not Available
Date Resident Turned in Keys	Not Available

Damage Summary				
Main Category	Sub Category	Charges Type	Note	Charges
KITCHEN	Cleaning Refrigerator	Clean		\$60.00
BEDROOMS	Floors / Carpet	Replace		\$0.00
Additional Damage Charges				
Total Charges			\$60.00	

LIVING ROOM:	
Walls / Outlets:	Ok
Ceilings / Lights:	Ok
Window:	Ok
Door / Closet:	Ok
Window coverings:	Ok
Other:	Ok
DINING ROOM:	
Walls / Outlets:	Ok
Ceilings / Lights:	Ok
Window:	Ok
Window coverings:	Ok
KITCHEN:	
Electric Meter:	Ok

Cabinets:	Ok
Cabinet Door:	Ok
Cabinet Shelf:	Ok
Cabinet Handle:	Ok
Counter Top:	Ok
Refrigerator (Freezer):	Ok
Refrigerator (Shelf and Bars):	Ok
Refrigerator (Drawers):	Ok
Refrigerator Crisper Glass/Plastic:	Ok
Cleaning Refrigerator:	Not Ok
Charges Type	Clean
Charges	
Comment	Fridge was not cleaned



Dishwasher Rack:	Ok
Dishwasher Silverware Holder:	Ok
Dishwasher Knob:	Ok
Fire Stops:	Ok
Formica/Tiles:	Ok
Stove Knob:	Ok
Microwave:	Ok
Cleaning of Stove:	Ok
Ceiling Lights:	Ok
Garbage Disposal:	Ok
Rubber Stopper:	Ok
Oven Door Handle:	Ok
Oven Racks:	Ok

Kitchen Sink:	Ok
Faucet Knobs:	Ok
Floors:	Ok
Faucet:	Ok
Drip Pan:	Ok
Range Hood:	Ok
Range Top:	Ok
Ceiling Light Fixture:	Ok
Backsplash:	Ok
Ceiling Fan:	Ok
Washer/Dryer:	Ok
Wall Outlets:	Ok
Window Coverings:	Ok
Other:	Ok
BEDROOMS:	
Walls / Outlets:	Ok
Ceilings / Lights:	Ok
Floors / Carpet:	Not Ok
Charges Type	Replace
Charges	
Comment	Hole in carpet and stained



Window:	Ok
Window coverings:	Ok
Door / Closet:	Ok
Other:	Ok
BATHROOM:	

Medicine Cabinet:	Ok
Mirror Cabinet:	Ok
Vanity Cabinet:	Ok
Sink:	Ok
Toilet Tank Cover:	Ok
Toilet Tank:	Ok
Toilet Bowl:	Ok
Complete Toilet:	Ok
Toilet Paper Holder:	Ok
Shower Head:	Ok
Tub Knob(s):	Ok
Shower Curtain Bar:	Ok
Towel Bar:	Ok
Tub Reglazing:	Ok
Counter Top:	Ok
Soap Dish (Sink):	Ok
Soad Dish (Tub):	Ok
Remove Mildew on Tiles:	Ok
Cleaning Bathroom:	Ok
Wall Outlets:	Ok
Ceiling Lights:	Ok
Floors:	Ok
Formica /Tile:	Ok
Cabinets / Mirror:	Ok
Window:	Ok
Other:	Ok
Is there signs of moisture from outside in the apartment?:	Ok
DOORS:	
Apartment Door:	Ok
Solid Core & Steel:	Ok
Frame:	Ok
Hollow:	Ok
CARPET:	
Shampoo 1 Bedroom:	Ok

Shampoo 2 Bedroom: Stain Removal: Ok Burns: Ok Deodorize: Ok Pet Treatment (Odor): Ok Replace Carpet 1 Bedroom: Ok Replace Carpet 2 Bedroom: Ok OVERALL: Signs of Moisture inside the apartment: Ok Resident		
Burns: Ok Deodorize: Ok Pet Treatment (Odor): Ok Replace Carpet 1 Bedroom: Ok Replace Carpet 2 Bedroom: Ok OVERALL: Signs of Moisture inside the apartment: Ok Signs of Moisture outside the apartment: Ok	Shampoo 2 Bedroom:	Ok
Deodorize: Ok Pet Treatment (Odor): Ok Replace Carpet 1 Bedroom: Ok Replace Carpet 2 Bedroom: Ok OVERALL: Signs of Moisture inside the apartment: Ok Signs of Moisture outside the apartment: Ok	Stain Removal:	Ok
Pet Treatment (Odor): Replace Carpet 1 Bedroom: Ok Replace Carpet 2 Bedroom: Ok OVERALL: Signs of Moisture inside the apartment: Ok Signs of Moisture outside the apartment: Ok	Burns:	Ok
Replace Carpet 1 Bedroom: Ok Replace Carpet 2 Bedroom: Ok OVERALL: Signs of Moisture inside the apartment: Ok Signs of Moisture outside the apartment: Ok	Deodorize:	Ok
Replace Carpet 2 Bedroom: Ok OVERALL: Signs of Moisture inside the apartment: Ok Signs of Moisture outside the apartment: Ok	Pet Treatment (Odor):	Ok
OVERALL: Signs of Moisture inside the apartment: Ok Signs of Moisture outside the apartment: Ok	Replace Carpet 1 Bedroom:	Ok
Signs of Moisture inside the apartment: Ok Signs of Moisture outside the apartment: Ok	Replace Carpet 2 Bedroom:	Ok
Signs of Moisture outside the apartment: Ok	OVERALL:	
	Signs of Moisture inside the apartment:	Ok
Resident	Signs of Moisture outside the apartment:	Ok
	Resident	

Lindy Community Representative Name Rafael Soto Ocasio
--



Technician	Rafael Soto Ocasio
Resident not available for signature	YES
Resident refused Signature	NO