

Move Out Inventory & Condition Form

Inspection Date	Technician	Property	Units
05-12-2025	Nilsa Reyes	Joshua House	G0108

Approved By	Nilsa Reyes
Resident Name	Krzysztof Paluchowski
Forwarding Mailing Address	600 Valley RoadApt A38 Warrington PA 18976
Date Resident Turned in Keys (For evictions - date all belongings were removed)	05-10-2025

Damage Summary			
Main Category	Charges		
Additional Damage Charges			
Total Charges \$0.		\$0.00	

LIVING ROOM:	
Ceilings / Lights:	Ok
Door / Closet:	Ok
Other:	Ok
Walls / Outlets:	Ok
Window:	Ok
Window coverings:	Ok

DINING ROOM:	
Ceilings / Lights:	Ok
Walls / Outlets:	Ok
Window:	Ok
Window coverings:	Ok

KITCHEN:	
----------	--

Backsplash:	Ok	
Cabinets:		
Cabinet Door:	Oł	τ
Cabinets:		
Cabinet Handle:	(Ok
Cabinets:		
Cabinet Shelf:	Ol	ζ
Ceiling Fan:	Ok	:
Ceiling Light Fixture:	Ok	
Ceiling Lights:	Ok	
Cleaning of Stove:	Ok	
Counter Top:	Ok	į
Dishwasher:		
Dishwasher Knob:		Ok
Dishwasher:		
Dishwasher Rack:		Ok
Dishwasher:		
Dishwasher Silverware Holder:		Ok
Drip Pan:	Ok	
Electric Meter:	Ok	
Faucet:	Ok	
Faucet Knobs:	Ok	
Floors:	Ok	
Formica/Tiles:	Ok	
Garbage Disposal:	Ok	
Is there a FireAvert red box, plug, and solenoid?:	Ok	
Kitchen Sink:	Ok	
Microwave:	Ok	
Other:	Ok	

Oven / Range:		01
Oven Cleaning:		Ok
Oven / Range:		
Oven door handle:		Ok
Oven / Range:		
Oven drip pan:		Ok
Oven / Range:		
Oven knobs:		Ok
Oven / Range:		
Oven Racks:		Ok
Oven / Range:		
Range burners:		Ok
Oven / Range:		
Range Hood:		Ok
Oven Door Handle:	O	k
Oven Racks:	O	k
Range Top:	O	k
Refrigerator (Freezer):	C	k
Rubber Stopper:	O	k
Stove Knob:	O	k
Vall Outlets:	O	k
Vasher/Dryer:	O	k
Vindow Coverings:	O	k
BEDROOMS:		
Ceilings / Lights:	С	k
Door / Closet:	С	k
Floors / Carpet:	С	k
Other:	C	k

Window:	Ok	
Window coverings:	Ok	

BATHROOM:	
Cabinets / Mirror:	Ok
Ceiling Lights:	Ok
Cleaning Bathroom:	Ok
Complete Toilet:	Ok
Counter Top:	Ok
Floors:	Ok
Formica /Tile:	Ok
Is there signs of moisture from outside in the apartment?:	Ok
Medicine Cabinet:	Ok
Mirror Cabinet:	Ok
Other:	Ok
Remove Mildew on Tiles:	Ok
Shower Curtain Bar:	Ok
Shower Head:	Ok
Sink:	Ok
Soad Dish (Tub):	Ok
Soap Dish (Sink):	Ok
Toilet Paper Holder:	Ok
Toilet Tank:	Ok
Towel Bar:	Ok
Tub Knob(s):	Ok
Tub Reglazing:	Ok
Vanity Cabinet:	Ok
Wall Outlets:	Ok
Window:	Ok

LOCKS:	
Door Knob:	Ok
Door Lock:	Ok
Ensure the apartment door has an automatic closure and closes properly. :	Ok

Fix Door when extra lock is removed:	Ok
Mail-Box Lock:	Ok

KEYS:	
Failure To Return Apartment Key:	Ok
Failure To Return Mailbox Key:	Ok

DOORS:	
Apartment Door:	Ok
Apartment Door closes automatically:	Ok
Frame:	Ok
Hollow:	Ok
Solid Core & Steel:	Ok

PAINTING:	
Border Removal (Per Room):	Ok
Holes in Walls (Each Hole):	Ok
Over Dark Colors (Per Room):	Ok
Wallpaper Removal (Per Room):	Ok

CARPET:	
Burns:	Ok
Deodorize:	Ok
Pet Treatment (Odor):	Ok
Replace Carpet 1 Bedroom:	Ok
Replace Carpet 2 Bedroom:	Ok
Shampoo 1 Bedroom:	Ok
Shampoo 2 Bedroom:	Ok
Stain Removal:	Ok

MISCELLANEOUS:	
Broken Window Glass (Per Pane):	Ok
Cabinet Equipment:	Ok
Carbon Monoxide Detector:	Ok
Cleaning of Apartment:	Ok
Clear Storage Locker:	Ok

Closet Shelves:	Ok
Common Area damaged during moveout:	Ok
Door Intercom System:	Ok
Exhaust Fan:	Ok
Fan Blades:	Ok
If fire stops have been installed throughout the property, ensure fire stops are installed.:	Ok
Light Globes:	Ok
Mini Blind(s) each:	Ok
Outside Lights:	Ok
Phone Jack:	Ok
Rallings:	Ok
Removal Of Bulk Items:	Ok
Remove Debris (Per Bag):	Ok
Sliding Mirror/Glass Door (2):	Ok
Smoke Detector Alarm:	Ok
Stoppage by foreign object in any drain:	Ok
Switch Plate Covers:	Ok
Thermostat Cover:	Ok
Vertical Blinds:	Ok
Vinly Tile Bathroom:	Ok
Vinly Tile Kitchen:	Ok
Window Screen(s) each:	Ok
Window Sills:	Ok

OVERALL:	
Signs of Moisture inside the apartment:	Ok
Signs of Moisture outside the apartment:	Ok

Resident	
----------	--

Lindy Community Representative Name	Nilsa Reyes
Technician	Nilsa Reyes
Resident not available for signature	YES