

Move Out Inventory & Condition Form

Inspection Date	Technician	Property	Units
05-17-2023	Marva Brown	Gateway Towers	B323

Approved By	Marva Brown
Resident Name	Marc Hill Jr
Forwarding Mailing Address	Transfer to B108
Date Resident Turned in Keys	05-07-2023

Damage Summary				
Main Category Sub Category Charges Type Note			Charges	
CARPET	Replace Carpet 1 Bedroom	Replace	carpet ruined less depreciation	\$320.00
Additional Damage Charges				
Total Charges			\$320.00	

Amenities to be added to this Unit	
Plank Flooring	

LIVING ROOM:	
Ceilings / Lights:	Ok
Door / Closet:	Ok
Other:	Ok
Walls / Outlets:	Ok
Window:	Ok
Window coverings:	Ok

DINING ROOM:	
Ceilings / Lights:	Ok
Walls / Outlets:	Ok

Window:	Ok		
Window coverings:	Ok		
KITCHEN:			
Backsplash:			Ok
Cabinets:			
Cabinet Door:	Ok		
	1		
Cabinets:			
Cabinet Handle:	Ok		
Cabinets:			
Cabinet Shelf:	Ok		
Ceiling Fan:			Ok
Ceiling Light Fixture:			Ok
Ceiling Lights:			Ok
Cleaning of Stove:			Ok
Counter Top:			Ok
Dishwasher:			
Dishwasher Knob:	Ok		
Dishwasher:			
Dishwasher Rack:	Ok		
Dishwasher:			
Dishwasher Silverware Holder:		Ok	
Drip Pan:			Ok
Electric Meter:			Ok
Faucet:			Ok
Faucet Knobs:			Ok
Floors:			Ok
Formica/Tiles:			Ok
Garbage Disposal:			Ok
Kitchen Sink:			Ok
Microwave:			Ok

Other:			Ok
Oven / Range:			
Oven Cleaning:	С)k	
Oven / Range:			
Oven door handle:		Ok	
Oven / Range:			
Oven drip pan:	О	k	
Oven / Range:			
Oven knobs:	Ok	ζ	
Oven / Range:			
Oven Racks:	Ok	ζ	
Oven / Range:			
Range burners:	С)k	
Oven / Range:			
Range Hood:	Ol	ζ	
Oven Door Handle:			Ol
Oven Racks:			Ol
Range Top:			Oŀ
Refrigerator (Freezer):			Ok
Rubber Stopper:			Ok
Stove Knob:			Oŀ
Verify that either a Fire Stop (under the microwave) or FireAvert (behind the stove) exists.:			Ol
Wall Outlets:			Oł
Washer/Dryer:			Ol
Window Coverings:			Ol
BATHROOM:			

BATHROOM:	
Cabinets / Mirror:	Ok
Ceiling Lights:	Ok
Cleaning Bathroom:	Ok

Complete Toilet:	Ok
Counter Top:	Ok
Floors:	Ok
Formica /Tile:	Ok
Is there signs of moisture from outside in the apartment?:	Ok
Medicine Cabinet:	Ok
Mirror Cabinet:	Ok
Other:	Ok
Remove Mildew on Tiles:	Ok
Shower Curtain Bar:	Ok
Shower Head:	Ok
Sink:	Ok
Soad Dish (Tub):	Ok
Soap Dish (Sink):	Ok
Toilet Paper Holder:	Ok
Toilet Tank:	Ok
Towel Bar:	Ok
Tub Knob(s):	Ok
Tub Reglazing:	Ok
Vanity Cabinet:	Ok
Wall Outlets:	Ok
Window:	Ok

LOCKS:	
Door Knob:	Ok
Door Lock:	Ok
Ensure the apartment door has an automatic closure and closes properly. :	Ok
Fix Door when extra lock is removed:	Ok
Mail-Box Lock:	Ok

KEYS:	
Failure To Return Apartment Key:	Ok
Failure To Return Mailbox Key:	Ok

DOORS:		
DOORS.		

Apartment Door:	Ok
Apartment Door closes automatically:	Ok
Frame:	Ok
Hollow:	Ok
Solid Core & Steel:	Ok

CARPET:	
Burns:	Ok
Deodorize:	Ok
Pet Treatment (Odor):	Ok
Replace Carpet 1 Bedroom:	Not Ok
Charges Type	Replace
Charges	
Comment	Carpet ruined



Replace Carpet 2 Bedroom:	Ok
Shampoo 1 Bedroom:	Ok
Shampoo 2 Bedroom:	Ok
Stain Removal:	Ok

MISCELLANEOUS:	
Broken Window Glass (Per Pane):	Ok
Cabinet Equipment:	Ok
Carbon Monoxide Detector:	Ok
Cleaning of Apartment:	Ok
Clear Storage Locker:	Ok
Closet Shelves:	Ok
Common Area damaged during moveout:	Ok

Door Intercom System:	Ok
Exhaust Fan:	Ok
Fan Blades:	Ok
If fire stops have been installed throughout the property, ensure fire stops are installed.:	Ok
Date of Installation	2021-05-17
Light Globes:	Ok
Mini Blind(s) each:	Ok
Outside Lights:	Ok
Phone Jack:	Ok
Rallings:	Ok
Removal Of Bulk Items:	Ok
Remove Debris (Per Bag):	Ok
Sliding Mirror/Glass Door (2):	Ok
Smoke Detector Alarm:	Ok
Stoppage by foreign object in any drain:	Ok
Switch Plate Covers:	Ok
Thermostat Cover:	Ok
Vertical Blinds:	Ok
Vinly Tile Bathroom:	Ok
Vinly Tile Kitchen:	Ok
Window Screen(s) each:	Ok
Window Sills:	Ok

OVERALL:	
Signs of Moisture inside the apartment:	Ok
Signs of Moisture outside the apartment:	Ok

Lindy Community Representative Name	Marva Brown
-------------------------------------	-------------

M-CL

Technician	Marva Brown
Resident not available for signature	YES