


## **Make Ready Checklist Inspection**

Inspection Date	Technician	Property	Units
05-28-2021	Peter Tester	450 Green Apartments	N200

MISCELLANEOUS:	
If there are sprinkler heads, are they painted?:	Yes
If there are sprinklers, are the sprinkler pipes painted?:	

Resident	test
----------	------



Lindy Community Representative Name	Peter Tester
-------------------------------------	--------------

fel

Technician	Peter Tester
Resident not available for signature	
Resident refused Signature	