

Make Ready Checklist Inspection

Inspection Date	Technician	Property	Units
06-01-2023	Travis Poston	Towers at Wyncote	PH01-3

LIVING ROOM:	
Ceilings / Lights:	Not Ok
Charges Type	
Charges	0
Comment	Ceiling light fixture is very old/ outdated. Please replace with updated casing



Door / Closet:	Ok
Other:	Ok
Plank Flooring:	Ok
Walls / Outlets:	Ok
Window:	Ok
Window coverings:	Ok

DINING ROOM:	
Ceilings / Lights:	Ok
Plank Flooring:	Ok
Walls / Outlets:	Ok
Window:	Ok

Window coverings:		Ok		
KITCHEN:				
Backsplash:				Ok
Cabinets:				
Cabinet Door:	0	k		
Cabinets:				
Cabinet Handle:		Ok		
Cabinets:				
Cabinet Shelf:	0)k		
Ceiling Fan:				Ok
Ceiling Light Fixture:				Ok
Ceiling Lights:				Ok
Cleaning of Stove:				Ok
Counter Top:				Ok
Dishwasher:				
Dishwasher Knob:		Ok		
Dishwasher:				
Dishwasher Rack:		Ok		
Dishwasher:				
Dishwasher Silverware Holder:			Ok	
Drip Pan:				Ok
Electric Meter:				Ok
Faucet:				Ok
Faucet Knobs:				Ok
Floors:				Ok
Formica/Tiles:				Ok
Garbage Disposal:				Ok
Kitchen Sink:				Ok
Microwave:				Ok
Other:				Ok

Oven / Range:	
Oven Cleaning:	Not Ok
Charges Type	
Charges	0
Comment	Clean drip marks on bottom oven/ drip pan



Oven / Range:	
Oven door handle:	Ok

Oven / Range:	
Oven drip pan:	Ok

Oven / Range:	
Oven knobs:	Ok

Oven / Range:	
Oven Racks:	Ok

Oven / Range:	
Range burners:	Ok

Oven / Range:	
Range Hood:	Ok

Oven Door Handle:	Ok
Oven Racks:	Ok
Range Top:	Ok
Refrigerator (Freezer):	Ok
Rubber Stopper:	Ok

Stove Knob:	Ok
Verify that either a Fire Stop (under the microwave) or FireAvert (behind the stove) exists.:	Ok
Wall Outlets:	Ok
Washer/Dryer:	Ok
Window Coverings:	Ok

BEDROOMS:	
Ceilings / Lights:	Not Ok
Charges Type	
Charges	0
Comment	Ceiling light fixture is very old/ outdated. Please replace with updated casing



Door / Closet:	Ok
Floors / Carpet:	Ok
Other:	Ok
Plank Flooring:	N/A
Walls / Outlets:	Ok
Window:	Ok
Window coverings:	Ok

BATHROOM:	
Cabinets / Mirror:	Ok
Ceiling Lights:	Ok
Cleaning Bathroom:	Ok
Complete Toilet:	Ok
Counter Top:	Ok
Floors:	Not Ok
Charges Type	

Charges	0
Comment	Baseboards under sink in hall bathroom rough



Formica /Tile:	Ok
Is there signs of moisture from outside in the apartment?:	Ok
Medicine Cabinet:	Ok
Mirror Cabinet:	Ok
Other:	Not Ok
Charges Type	
Charges	0
Comment	Door hinge in hall bathroom has been painted over many times and paint is peeling off/ looks bad



Plank Flooring:	Ok
Remove Mildew on Tiles:	Ok
Shower Curtain Bar:	Ok
Shower Head:	Ok
Sink:	Ok
Soad Dish (Tub):	Ok
Soap Dish (Sink):	Ok
Toilet Paper Holder:	Ok
Toilet Tank:	Ok

Towel Bar:	Ok
Tub Knob(s):	Ok
Tub Reglazing:	Ok
Vanity Cabinet:	Ok
Wall Outlets:	Ok
Window:	Ok

LOCKS:	
Door Knob:	Ok
Door Lock:	Ok
Ensure the apartment door has an automatic closure and closes properly. :	Ok
Fix Door when extra lock is removed:	Ok
Mail-Box Lock:	Ok

KEYS:	
Failure To Return Apartment Key:	Ok
Failure To Return Mailbox Key:	Ok

DOORS:	
Apartment Door:	Ok
Apartment Door closes automatically:	Ok
Frame:	Ok
Hollow:	Ok
Solid Core & Steel:	Ok

PAINTING:	
Border Removal (Per Room):	Ok
Holes in Walls (Each Hole):	Ok
Over Dark Colors (Per Room):	Ok
Wallpaper Removal (Per Room):	Ok

CARPET:	
Burns:	Ok
Deodorize:	Ok
Pet Treatment (Odor):	Ok
Replace Carpet 1 Bedroom:	Ok

Replace Carpet 2 Bedroom:	Ok
Shampoo 1 Bedroom:	Ok
Shampoo 2 Bedroom:	Ok
Stain Removal:	Ok

MISCELLANEOUS:	
Broken Window Glass (Per Pane):	Ok
Cabinet Equipment:	Ok
Carbon Monoxide Detector:	Ok
Cleaning of Apartment:	Ok
Clear Storage Locker:	Ok
Closet Shelves:	Ok
Common Area damaged during moveout:	Ok
Confirm you have installed or there is in place a stainless steel toilet tank water connector.:	Ok
Door Intercom System:	Ok
Exhaust Fan:	Ok
Fan Blades:	Ok
If fire stops have been installed throughout the property, ensure fire stops are installed.:	Ok
Date of Installation	2023-06-01
Light Globes:	Ok
Mini Blind(s) each:	Ok
Outside Lights:	Ok
Phone Jack:	Ok
Rallings:	Ok
Removal Of Bulk Items:	Ok
Remove Debris (Per Bag):	Ok
Sliding Mirror/Glass Door (2):	Ok
Smoke Detector Alarm:	Ok
Stoppage by foreign object in any drain:	Ok
Switch Plate Covers:	Ok
Thermostat Cover:	Ok
Vertical Blinds:	Ok
Vinly Tile Bathroom:	Ok
Vinly Tile Kitchen:	Ok

Window Screen(s) each:	Ok	
Window Sills:	Ok	

OVERALL:	
Signs of Moisture inside the apartment:	Ok
Signs of Moisture outside the apartment:	Ok

Resident	Travis Poston

WA AT

Lindy Community Representative Name

Travis Poston

1	
	1/54
My	

Technician	Travis Poston
Resident not available for signature	