

## **Make Ready Checklist Inspection**


Inspection Date	Technician	Property	Units
06-07-2021	Kim Crawford Gardens of Mt. Airy		D09

OVERALL:	
Signs of Moisture inside the apartment:	Ok
Signs of Moisture outside the apartment:	Ok

Resident
----------

Lindy Community Representative Name

Kim Crawford



Technician	Kim Crawford
Resident not available for signature	
Resident refused Signature	