

## **Move Out Inventory & Condition Form**

| Inspection Date | Technician | Property    | Units |
|-----------------|------------|-------------|-------|
| 06-04-2021      | Paul Oneto | Meadowbrook | 842   |

| Resident Name                | Estate of     |
|------------------------------|---------------|
| Forwarding Mailing Address   | Not Available |
| Date Resident Turned in Keys | 06-03-2021    |

| Damage Summary            |                             |              |               |         |
|---------------------------|-----------------------------|--------------|---------------|---------|
| Main Category             | Sub Category                | Charges Type | Note          | Charges |
| CARPET                    | Replace Carpet 2<br>Bedroom | Replace      | Carpet damage | \$0.00  |
| Additional Damage Charges |                             |              |               |         |
|                           |                             |              | Total Charges | \$0.00  |

| CARPET:                   |         |
|---------------------------|---------|
| Replace Carpet 2 Bedroom: | Not Ok  |
| Charges Type              | Replace |
| Charges                   |         |
| Comment                   | Stains  |



| Resident |  |
|----------|--|
|----------|--|

| Lindy Community Representative Name | Paul Oneto |
|-------------------------------------|------------|
| Lindy Community Representative Name | Paul Oneto |



| Technician                           | Paul Oneto |
|--------------------------------------|------------|
| Resident not available for signature | YES        |